Apple IIGS: Remove AppleTalk Before Internal Test

```
Revised:        7/25/91
Security:       Everyone
```

Apple IIGS: Remove AppleTalk Before Internal Test

===

Article Created: 1 May 1991
Article Last Reviewed:
Article Last Updated:

TOPIC ---

I performed an internal test on my Apple IIGS using the
Command-Control-Option-Reset key sequence. Soon after I did this, other
computers were disconnected from the network. Did my Apple IIGS internal
test cause the problem?

DISCUSSION --

Yes. When performing an internal test on an Apple IIGS that is on an
AppleShare network, be sure to disconnect the network connector. Failure
to do so will cause severe communication problems with other nodes, and
will usually result in other computers becoming electronically
disconnected from the network.

Copyright 1991, Apple Computer, Inc.

Tech Info Library Article Number:7444